AVAYA

Title: End of Sale (EoS) Notification for INTUITY AUDIX LX (IALX) R1

Notification Update: July 27, 2007
Additions to R1.1 will continue to be offered until further notice.

Notification Date: June 8, 2007
With the launch of INTUITY AUDIX LX R2, Avaya will end sale of INTUITY AUDIX R1.

Effective August 8, 2007 Avaya will stop accepting quotations and new orders for new system sales or orders for additions and expansions of INTUITY AUDIX LX R1.

INTUITY AUDIX LX R1 will follow standard Avaya manufacturer's support policy.
The End of Manufacturer Support for INTUITY AUDIX LX R1 will be August 8, 2009

Discontinued SAP material codes

SAP Material Code	DESCRIPTION	End of Sale Date
174642	IALX US/CANADA 100X4 SYS R1	August 8, 2007
174643	IALX US/CANADA 300X8 SYS R1	August 8, 2007
174644	IALX US/CANADA 500X12 SYS R1	August 8, 2007
175726	IALX 100X4 SYS (EMEA)	August 8, 2007
176338	IALX 100X4 TO 300X 8 SYS EXP BD A	August 8, 2007
176339	IALX 100X4 TO 500X12 SYS EXP BD	August 8, 2007
176340	IALX 300X8 TO 500X12 EXPBD	August 8, 2007
176341	IALX 100X4 TO 300X8 SYS EXP BD B	August 8, 2007
176342	IALX 100X4 TO 500X12 SYS EXP BD B	August 8, 2007
176343	IALX 300X8 TO 500X12 EXP BD	August 8, 2007
176356	IALX PT CD (TYPE A) W/PT RTU'S	August 8, 2007
176357	IALX PT CD (TYPE B) W/PT RTU'S	August 8, 2007
176358	IALX ACTIVATION FOR ADDL AM	August 8, 2007
176359	IALX MEDIA	August 8, 2007
176783	AM CARD 4PT ANALOG TA	August 8, 2007
176784	AM CARD 4PT ANALOG TA	August 8, 2007
182759	IALX SFTW APPL LIC LIC:DS	August 8, 2007
186027	IALX 100 SEATS X 4PT BNDL LIC:NU,CU	August 8, 2007
186028	IALX 300 SEATS X 8PT LIC BNDL	August 8, 2007
186029	IALX 500 SEATS X 12PT BNDL LIC:NU,CU	August 8, 2007
700211444	IALX MN MODEM SERIAL	August 8, 2007
700231079	IALX SFTW SYS REPLACEMENT R1.0	August 8, 2007

700337108	IALX SRVR OFFER CODE SFTW	August 8, 2007
700337116	IALX DOC BUNDL R1.1	August 8, 2007
700211444	IALX MN MODEM SERIAL	August 8, 2007
700402779	AM S3210R SERVER RHS	August 8, 2007

Please note: There are other support material codes that may be discontinued as a result of the end of sale.

Replacement Product:
The successor platform for the INTUITY AUDIX LX R1 is INTUITY AUDIX LX R2.

Sap Material Code	Description	Launch Date
202460	IALX R2 APPLICATION LICENSE	May 7, 2007
202461	IALX R2 APPLICATION LIC R1 UPG	May 7, 2007
202462	IALX R2 LIC 1ST VC MBX NEW 1-5	May 7, 2007
202463	IALX R2 LIC 1ST VC MBX NEW 6-10	May 7, 2007
202464	IALX R2 LIC 1ST VC MBX NEW 11-25	May 7, 2007
202465	IALX R2 LIC 1ST VC MBX NEW 26-50	May 7, 2007
202466	IALX R2 LIC 1ST VC MBX NEW 51-100	May 7, 2007
202467	IALX R2 LIC 1ST VC MBX NEW 101-251	May 7, 2007
202468	IALX R2 LIC 1ST VC MBX NEW 251-500	May 7, 2007
202469	IALX R2 LIC 1ST VC MBX NEW 501-1000	May 7, 2007
202470	IALX R2 LIC 1ST VC MBX NEW 1000+	May 7, 2007
202471	IALX R2 LIC 1ST VC MBX ADD 1-5	May 7, 2007
202472	IALX R2 LIC 1ST VC MBX ADD 6-10	May 7, 2007
202473	IALX R2 LIC 1ST VC MBX ADD 11-25	May 7, 2007
202474	IALX R2 LIC 1ST VC MBX ADD 26-50	May 7, 2007
202475	IALX R2 LIC 1ST VC MBX ADD 51-100	May 7, 2007
202476	IALX R2 LIC 1ST VC MBX ADD 101-250	May 7, 2007
202477	IALX R2 LIC 1ST VC MBX ADD 251-500	May 7, 2007
202478	IALX R2 LIC 1ST VC MBX ADD 501-1000	May 7, 2007
202479	IALX R2 LIC 1ST VC MBX ADD 1000+	May 7, 2007
202480	IALX R2 LIC 1ST VCMBX UPG R1 1-5	May 7, 2007
202481	IALX R2 LIC 1ST VCMBX UPG R1 6-10	May 7, 2007
202482	IALX R2 LIC 1ST VCMBX UPG R1 11-25	May 7, 2007
202483	IALX R2 LIC 1ST VCMBX UPG R1 26-50	May 7, 2007
202484	IALX R2 LIC 1ST VCMBX UPG R1 51-100	May 7, 2007
202485	IALX R2 LIC 1ST VCMBX UPG R1 101-250	May 7, 2007
202486	IALX R2 LIC 1ST VCMBX UPG R1 251-500	May 7, 2007
202520	IALX R2 LIC 1ST VCMBXUPG R1 501-1000	May 7, 2007
202521	IALX R2 LIC 1ST VCMBX UPG R1 1000+	May 7, 2007
700427560	IALX APPLICATION MEDIA R2.0	May 7, 2007

700427529	AM S3210R SERVER	May 7, 2007
700427537	AM MODEM SERIAL MULTITECH	May 7, 2007
700427545	AM S3210R MISC CMPTS KIT US/CAN	May 7, 2007
700427552	AM S3210R MISC CMPTS KIT INTL	May 7, 2007
700427420	AM 6-POSITION RIBBON CABLE S3210R	May 7, 2007
700427578	IALX DOCUMENTATION KIT R2	May 7, 2007

Migration Strategy

Customers that have an IALX R1/R1.1 can upgrade to a later release of IALX. If the existing hardware platform is an S3210, customers will need to upgrade the hardware to R2 specifications. In the case of an existing LX1000 system a server replacement will be required.

Product documentation is available for download at the following URL:
http://support.avaya.com/japple/css/japple?PAGE=ProductArea&temp.productID=13
6319&temp.releaseID=315635

INTUITY AUDIX LX R1 Support Schedule

| INTUITY AUDIX LX R1 End of Sale (EOS) Date | August 8, 2007 |
| End of Manufacturer Support | August 8, 2009 |

Reminders:
INTUITY AUDIX LX 1000 and S3210 Server Support Schedule

INTUITY AUDIX LX 1000	
End of Sale	June 2003
End of Manufacturer Support	June 2006
INTUITY AUDIX S3210 Server	
End of Sale	June 2006
End of Manufacturer Support	June 2009

Service and Warranty

Avaya will continue to honor previously executed enhanced warranty, post-warranty and service contracts in accordance with the terms of those agreements. Avaya is not responsible for any support or maintenance commitments made by BusinessPartners or other service providers. Additional information concerning Avaya Services can be found on the Services Offer Information Web site.

Product Information

Additional Information about INTUITY AUDIX LX Multimedia Messaging Solution can be found at:

http://www.avaya.com/gcm/master-usa/en-
us/products/offers/intuity_audix_lx_multimedia_messaging_server01.htm