

Title: End of Sale for Modular Messaging R3.0 with the Avaya Message Storage Server (MSS) and Exchange Message Store (Revised April 21, 2008)

Notification Date: July 23, 2007

With the General Availability (GA) of Modular Messaging Release 3.1, Avaya will End of Sale software media, licenses, and hardware for all new system sales of Avaya Modular Messaging Release R3.0 and upgrades to R3.0.

Effective **October 31, 2007** Avaya will no longer allow new quotations or orders for new systems sales of Modular Messaging R3.0 and upgrades to R3.0.

REVISED: Avaya will allow orders for additions and expansions of seat licenses to existing systems of Modular Messaging R3.0 systems until Modular Messaging R3.0 enters End of Manufacture Support.

Discontinued SAP Codes

The following SAP codes are discontinued beginning October 31, 2007 for new R3.0 system sales and upgrades to R3.0. The next major section identifies those codes that are discontinued for new system sale, but continue to be available for aftermarket expansions/additions.

| SAP Code | Description | |
|------------------------|----------------------------------|--|
| | • | |
| Modular Messaging R3.0 | | |
| New / Upgrade Seats | | |
| | nd Unified Mail (Exchange) | |
| 193328 | MM LIC 1 SEAT VOICE MBX 1-5 | |
| 193329 | MM LIC 1 SEAT VOICE MBX 6-10 | |
| 193330 | MM LIC 1 SEAT VOICE MBX 11-25 | |
| 193331 | MM LIC 1 SEAT VOICE MBX 26-50 | |
| 193332 | MM LIC 1 SEAT VOICE MBX 51-100 | |
| 193333 | MM LIC 1 SEAT VOICE MBX 101-250 | |
| 193334 | MM LIC 1 SEAT VOICE MBX 251-500 | |
| 193335 | MM LIC 1 SEAT VOICE MBX 501-1000 | |
| 193336 | MM LIC 1 SEAT VOICE MBX 1001+ | |
| 193341 | MM LIC 1 SEAT VMBX UPGD 1-5 | |
| 193342 | MM LIC 1 SEAT VMBX UPGD 6-10 | |
| 193343 | MM LIC 1 SEAT VMBX UPGD 11-25 | |
| 193344 | MM LIC 1 SEAT VMBX UPGD 26-50 | |
| 193345 | MM LIC 1 SEAT VMBX UPGD 51-100 | |
| 193346 | MM LIC 1 SEAT VMBX UPGD 101-250 | |
| 193347 | MM LIC 1 SEAT VMBX UPGD 251-500 | |
| 193348 | MM LIC 1 SEAT VMBX UPGD 501-1000 | |
| 193349 | MM LIC 1 SEAT VMBX UPGD 1001+ | |
| 193350 | MM LIC 1 SEAT UNIFD MBX 1-5 | |
| 193351 | MM LIC 1 SEAT UNIFD MBX 6-10 | |
| 193352 | MM LIC 1 SEAT UNIFD MBX 11-25 | |
| 193353 | MM LIC 1 SEAT UNIFD MBX 26-50 | |
| 193354 | MM LIC 1 SEAT UNIFD MBX 51-100 | |
| 193355 | MM LIC 1 SEAT UNIFD MBX 101-250 | |
| 193356 | MM LIC 1 SEAT UNIFD MBX 251-500 | |
| 193357 | MM LIC 1 SEAT UNIFD MBX 501-1000 | |



| 193358 | MM LIC 1 SEAT UNIFD MBX 1001+ | |
|------------------------|--|--|
| 193449 | MM LIC 1 SEAT UNFDMBX MMIP 1-5 | |
| 193362 | MM LIC 1 SEAT UNIFD MBX UPGD 1-5 | |
| 193363 | MM LIC 1 SEAT UNIFD MBX UPGD 6-10 | |
| 193364 | MM LIC 1 SEAT UNIFD MBX UPGD 11-25 | |
| 193365 | MM LIC 1 SEAT UNIFD MBX UPGD 26-50 | |
| 193366 | MM LIC 1 SEAT UNIFD MBX UPGD 51-100 | |
| 193367 | MM LIC 1 SEAT UNIFDMBX UPGD 101-250 | |
| 193368 | MM LIC 1 SEAT UNIFDMBX UPGD 251-500 | |
| 193369 | MM LIC 1 SEAT UNFDMBX UPGD 501-1000 | |
| 193370 | MM LIC 1 SEAT UNIFD MBX UPGD 1001+ | |
| 100010 | THE LIGHT SEAT STATE MEAN OF SEATON | |
| Modular Messa | aging R3.0 | |
| New Survivab | | |
| Voice Mailbox | and Unified Mail (Exchange) | |
| 200960 | MM R3.0 LIC 1 ST VMBX SURV 1-5 | |
| 200961 | MM R3.0 LIC 1 ST VMBX SURV 6-10 | |
| 200962 | MM R3.0 LIC 1 ST VMBX SURV 11-25 | |
| 200963 | MM R3.0 LIC 1 ST VMBX SURV 26-50 | |
| 200964 | MM R3.0 LIC 1 ST VMBX SURV 51-100 | |
| 200965 | MM R3.0 LIC 1 ST VMBX SURV 101-250 | |
| 200966 | MM R3.0 LIC 1 ST VMBX SURV 251-500 | |
| 200967 | MM R3.0 LIC 1 ST VMBX SURV 501-1000 | |
| 200968 | MM R3.0 LIC 1 ST VMBX SURV 1001+ | |
| 200987 | MM R3.0 LIC 1 ST UFMBX SURV 1-5 | |
| 200988 | MM R3.0 LIC 1 ST UFMBX SURV 6-10 | |
| 200989 | MM R3.0 LIC 1 ST UFMBX SURV 11-25 | |
| 200990 | MM R3.0 LIC 1 ST UFMBX SURV 26-50 | |
| 200991 | MM R3.0 LIC 1 ST UFMBX SURV 51-100 | |
| 200992 | MM R3.0 LIC 1 ST UFMBX SURV 101-250 | |
| 200993 | MM R3.0 LIC 1 ST UFMBX SURV 251-500 | |
| 200994 | MM R3.0 LIC 1 ST UFMBX SURV 501-1000 | |
| 200995 | MM R3.0 LIC 1 ST UFMBX SURV 1001+ | |
| | | |
| Modular Messa | | |
| Licenses - MAS | . 9 | |
| 190922 | MM MAS APP LIC R3 UPG EXCH CUST SVR MM MAS APP LIC R3 UPG DOM CUST SVR | |
| 190923 | | |
| 190924 190925 | MM MAS APP LIC R3 UPG EXCH AV SVR MM MAS APP LIC R3 UPG DOM AV SVR | |
| 190925 | MM MAS APP LIC R3 UPG AV STR AND SVR | |
| 190920 | IVIIVI IVIAS AFF LIC NO OFG AV STN AIND SVN | |
| Modular Messa | aging R3.0 | |
| | ograde Disks (from R1/R2) | |
| 700407737 | MM R3 MAS UPG DISK W BT IMG AV STR | |
| 700407745 | MM R3 MAS UPG DSK /W BTIMG EXCH AVSV | |
| · | | |
| Modular Messaging R3.0 | | |
| License – MSS | | |
| Media - MSS | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | |
| 190921 | MM MSS APP LIC R3 AVAYA SVR | |
| 190927 | MM MSS APP LIC R3 UPG AVAYA SVR | |
| 700376171 | MM MSS MED R3.0 /W APP MBM WEBCLNT | |



SAP Codes Discontinued for New System Sales Available for Aftermarket Expansions/Additions

The following SAP codes will not be available for new system sales. These SAP codes will be available to support aftermarket expansions/additions only.

| SAP Code | Description | | |
|--|---|--|--|
| Modular Messag | ing R3.0 | | |
| MMIP Seats | | | |
| Discontinued for New / Upgrade System Sale | | | |
| | bility for MMIP Seat additions / expansions | | |
| 193414 | MM LIC 1 SEAT VMBX MMIP 1-5 | | |
| 193415 | MM LIC 1 SEAT VMBX MMIP 6-10 | | |
| 193446 | MM LIC 1 SEAT VMBX MMIP 11-25 | | |
| 193447 | MM LIC 1 SEAT VMBX MMIP 26-50 | | |
| 193448 | MM LIC 1 SEAT VMBX MMIP 51-100 | | |
| 193337 | MM LIC 1 SEAT VMBX MMIP 101-250 | | |
| 193338 | MM LIC 1 SEAT VMBX MMIP 251-500 | | |
| 193339 | MM LIC 1 SEAT VMBX MMIP 501-1000 | | |
| 193340 | MM LIC 1 SEAT VMBX MMIP 1001+ | | |
| 193450 | MM LIC 1 SEAT UNFDMBX MMIP 6-10 | | |
| 193451 | MM LIC 1 SEAT UNFDMBX MMIP 11-25 | | |
| 193452 | MM LIC 1 SEAT UNFDMBX MMIP 26-50 | | |
| 193453 | MM LIC 1 SEAT UNFDMBX MMIP 51-100 | | |
| 193454 | MM LIC 1 SEAT UNFDMBX MMIP 101-250 | | |
| 193359 | MM LIC 1 SEAT UNFDMBX MMIP 251-500 | | |
| 193360 | MM LIC 1 SEAT UNFDMBX MMIP 501-1000 | | |
| 193361 | MM LIC 1 SEAT UNIFD MBX MMIP 1001+ | | |
| | | | |
| Modular Messag | ing R3.0 | | |
| License – MAS | | | |
| | New / Upgrade System Sale | | |
| | bility for Server additions / expansions | | |
| 190916 | MM MAS APP LIC R3 EXCH CUST SVR | | |
| 190917 | MM MAS APP LIC R3 DOMINO CUST SVR | | |
| 190918 | MM MAS APP LIC R3 EXCH AV SVR | | |
| 190919 | MM MAS APP LIC R3 DOMINO AV SVR | | |
| 190920 | MM MAS APP LIC R3 AV STORE AND SVR | | |
| Modulos Mass = = | ing D2 0 | | |
| Modular Messaging R3.0 | | | |
| Media Discontinued for New / Upgrade System Sale | | | |
| Continued availability for Server additions / expansions | | | |
| 700376148 | MM APP MED R3.0 EX CUST SVR | | |
| 700376163 | MM MAS MED W\OS R3.0 AV EX AVSVR | | |
| 700383086 | MM MAS MED W\OS R3 AV STORE AV SVR | | |
| 700383276 | MM OS BT MED R3 EML\TRC OLA WEB AVSV | | |
| 700383284 | MM OS BT MED R3 AVSTR TRC SVR AVSVR | | |
| 700376189 | MM R3 DOCUMENTATION KIT | | |
| 100010109 | WINT TO DOODIVILIATE TOTALL | | |



In continuing to extend value to Modular Messaging customers, Avaya will offer Modular Messaging R4.0. This release will provide numerous enhancements to Release 3.0. Modular Messaging R3.0 systems can be upgraded to Modular Messaging R4.0 directly.

For additional information regarding Modular Messaging R4.0 and upgrading your current Messaging System contact your Avaya Representative or Authorized Business Partner.

Schedule

| End of Sale (EoS) for New Systems | 10/31/2007 |
|---|---|
| End of Sale (EoS) for Additions and Expansions of seat licenses | 1 year (10/31/2008) or next Major Release (Modular Messaging 5.0), which ever is later |
| End of Sale (EoS) for Additions and Expansions of hardware | 8/5/2009 |
| Minimum Period of Software Support Availability after EoS | 1 year (10/31/2008) or next Major Release (Modular Messaging 5.0), which ever is later |
| Minimum Period of Hardware Support Availability after EoS | 3 years |

Minimum Period of Support Availability

The Minimum Period of Support availability represents the minimum period of time after the product end of sale date, during which Avaya will make available support for the product per the Avaya Manufacturer Support commitment. The Avaya Manufacturer Support Policy can be found at the following link:

http://support.avaya.com/elmodocs2/prodtran/Avaya Manufacturer Support Policy 09302007.pdf

Support may be extended past that period at the discretion of Avaya Services, Business Partners or other service providers. For additional information concerning long term support please contact your Service Provider.

Service and Warranty

Avaya will continue to honor previously executed enhanced warranty, post-warranty and service contracts in accordance with the terms of those agreements. Avaya is not responsible for any support or maintenance commitments made by Business Partners or other service providers. Additional information concerning Avaya Services can be found on the Services Offer Information Web site.

Avaya Services reserves the right to support this product at its discretion, as it is deemed appropriate.

For additional Information about Avaya Solutions please visit the Solutions area on the Enterprise Portal.